







## REPUESTOS HIDRAULICOS

CODIGO		PRECIO NETO	PRECIO FACT.
<b>RCCD00890</b>	 CIL.MAESTRO DC ø 20.64 DIAT DUNA/UNO h.99 Reempl.ATE 5766	<b>92,50</b>	132,14
<b>RCCE00041</b>	 CIL.MAESTRO EMBR. ø 19.05 M.BENZ L608 d.76 M.BENZ L708 d.87	<b>59,00</b>	84,28
<b>RCCR00163</b>	 CIL.RUEDA M.BENZ L708E/LO708 D/I	<b>43,00</b>	61,43
<b>RCCR02010</b>	 CIL.RUEDA FORD COURIER ø 22.2 D/I	<b>30,00</b>	42,86
<b>RCCR23244</b>	 CIL.RUEDA M.BENZ 113LA/321/OH 0352	<b>74,00</b>	105,71
<b>RCFD00030</b>	 MORDAZA F4000 TRAS.IZQ.	<b>580,00</b>	828,57

LOS PRECIOS NO INCLUYEN IVA,  
 ESTÁN SUJETOS A MODIFICACIONES SIN PREVIO AVISO

**Condición de pago : 20 días fecha factura**

**Descuento contado 3 %**